

All COR ISO Recommendations

Latent Condition, Seismic and ISS

Friday, October 12, 2012 12:37:15 PM

Type	Rec #	ABU	Unit	Year (I/R)	LC or ISS Question #	LC Question ISS Question Seismic Area	Observation	Recommendation	Resolution	Due Date	Assigned To	Status
Latent Condition	687	RLOP	HNF	2011	3-2	Are remote switches for different systems separated by sufficient distance to prevent operation of the wrong system during stressful situations?	Most switches are on the DCS system and are arranged to prevent inadvertent operation. There is a concern that similar numbering of CMC switches may cause confusion between LNF and HNF panels. (This also applies to LNC/HNC.)	Consider adding some method for highlighting difference between LNF and HNF CMC panels. (This also applies to LNC/HNC.)	A meeting with an Operations OA rep from each ABU was held to discuss this issue on February 9th, 2012. The outcome was to install informational bakelite tags to clearly identify each work station CMC panel. RLOP information bakelite tags were installed March 13th, 2012.	3/23/2012	Seidlitz, Michael R.	Completed